## 1. Identification of the Substance and Company

# VERIFY™ Vaporized VH2O2 Process Indicators

**Product No. See List Below**
**SDS No. S142UK**

**NFPA 704 HAZARD RATING:**
**HEALTH: 0**
**FIRE: 0**
**REACTIVITY: 0**

**Prepared by: M. Ebers**
asksteris_msds@steris.com
**Date Created: 03/13/2008 Date Revised: 05/17/2016 Date Reviewed: NA**

STERIS Corporation, P.O. Box 147, St. Louis, Mo 63166, US
Emergency Telephone No. 1-314-535-1395 (STERIS); 1-800-424-9300 (CHEMTREC)
Telephone Number for information: 1-800-548-4873 (Customer Service – Healthcare Products)

Albert Browne Limited, Chancery House, 190 Waterside Road, Hamilton Industrial Park, Leicester, LE5 1QZ, UK
Emergency Phone No: +44 (0) 1895 622 639
Product/Technical Information Phone No: +44 (0) 116 276 8636

| PRODUCT NAME: | PRODUCT NUMBER: |
|---|---|
| Verdoc™ Vaporized VH2O2 Record Card with process indicator | RK033 |
| Verdoc™ HPI Vaporized VH2O2 Record Card with process indicator | RK053 |
| VERIFY™ Vaporized VH2O2 Process Indicator | PCC046 |
| VERIFY™ HPI Vaporized VH2O2 Process Indicator | PCC056 |
| VERIFY™ Vaporized VH2O2 Process Indicator Adhesive Label | PCC048 |
| VERIFY™ HPI Vaporized VH2O2 Process Indicator Adhesive Label | PCC057 |
| VERIFY™ HPU Chemical Indicator | PCC061 |
| VERIFY™ HPI Chemical Indicator | PCC062 |
| SHIPPING INFORMATION: | NOT RESTRICTED |

These products are NOT hazardous products according to the OSHA Hazard Communication Standard, 29 CFR 1910.1200.

The indicator products listed are manufactured without natural rubber, latex and dry natural rubber.

The indicator products listed are manufactured using materials that are not derived from animal sources.

**In the case of accidental exposure, take the following precautionary measures:**
**EYES:** Immediately flush eyes with plenty of water for 15 minutes. Get medical attention if irritation persists.
**SKIN:** Immediately wash with soap and water. Get medical attention if irritation develops.
**INGESTION:** Give water to drink and get medical advice.
**INHALATION:** Remove to fresh air. Get medical attention for any breathing difficulty.

**Chemical Monitoring Strips Handling and Disposal:**
**Handling and Storage Precautions:** Keep box tightly closed. Store at 6°C (43°F) to 30°C (86 °F) and 30-80% relative humidity.
**Waste Disposal Methods:** Dispose of used/expired indicators and boxes in trash receptacle in accordance with federal, state, and local regulations.

*The information on this sheet is not a specification and does not guarantee specific properties. The information is intended to provide general knowledge as to health and safety based upon our knowledge of the handling, storage and use of the product. It is not applicable to unusual or non-standard uses of the product or where instruction or recommendations are not followed.*